Appendix 4 – Internal Audit Process Checklist

1	Test or Calibration	to Squares	o Number	Date of Audit		Name of Bill Jones	Pass or Fail
1	Dye Penetrant Testing					Inspector, ASNT level II 4/12/2011	Puss
2	ex Magnetic Particle Inspection			1/18/18	Magnetic Particle Test Unit. Last calibrated 5/15/2017	Fred Smith Inspector NADCAP Level II 2/15/2015	Pass
3	e.g. Radiography		Radiographic Test	1/19/18		Reggie Brown X-ray Tech. ASNT level II	Pass
5							
6							
7							
8							
9							
10							

Commented [170251]: Select a number of tests or calibrations to audit during each internal audit.

Commented [170252]: Include the full name of the test or calibration.

Commented [170254]: Give the name, number and

Commented [170255]: List all

Commented [170253]: include name, number and year of publishing the specification.

Commented [170257]: Give the audit result.

Commented [170256]: Show name, job title and evidence of qualification of person.